Oil Field Environmental Incident Summary

Responsible Party: BUCKHORN ENERGY SERVICES, LLC **Well Operator:** BUCKHORN ENERGY SERVICES, LLC

Well Name: LARMER 6-6

Field Name: HOFFLUND Well File #: 8981

Date Incident:10/13/2014Time Incident:17:10Facility ID Number:County:WILLIAMSTwp: 154Rng: 95Sec: 6Qtr:

Location Description:

Submitted By: Nancy Roberts Received By:

Contact Person: Nancy Roberts

5613 DTC Parkway Suite 800 Greenwood Village, CO 80111

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 17 Barrels 16 Barrels 16 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 1/13/2017 Clean Up Concluded: 10/16/2014

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

The water was immediately picked up, so should be no environmental impacts.

Action Taken or Planned:

Immediately picked up water spilled, replaced gasket.

Wastes Disposal Location: Water was put back into system.

Agencies Involved:

Updates

Date: 10/27/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to on-location valve/piping leak, remained on location within the diking according to the report. NDIC retains oversight.